Title:	**Steam-Generator Control and Error Flags**		ID:
			154
27.09.18	**Response:**	**Model:**	**Author:**
		-	*CMa*

SteamGene Heater output: 514

SteamGene Heater feed-back: 202

SteamGene Heater failure: 4911

SteamGene Heater Timeout error code: #77

SteamGene Heater Timeout: T51

SteamGene Blink detection delay: T76