

Title:	Align Transfer Station	ID:	
		0007	
Date in:	Response:	Model:	Author:
2003-07-01	2003-07-01	-	CMa

Q:

We receive the transfer station and have the incubator repainted.

For assembly of the slide station we need to drill 2 holes.

Could you provide urgently a drawing with the diameter and position of the holes.

A:

The best is if you make the handler stretch out the shovel through the Gate at it lower transfer position. You may then align the Transferstation. To do so I added the StxFer program.